IN 31703

TOR: 09/15303Z JAN 69 DGW

		S E C R E T 090905Z JAN 69 CITE 25X1A	1
25X1A	diggs.	PRIORITY	
25X1A	es <b>an</b>	IDEALIST	
		1. DURING PAST FEW YEARS 3 KNOWN TURBINE FAILURES HAVE	
25X1A	ejune#	OCCURRED. DOES ANY DATA EXIST ON ANY OF THESE	
	(Miller)	INCIDENTS TO SHOW TIME, HISTORY OF ENGINE RPM AND EGT FOLLOWING	
25X1A	***************************************	FAILURE. IF NO DATA AVAILABLE, CAN ANY OF PILOTS INVOLVE	D
	(Many)	RECALL THE RATE OF ENGINE DECAY AND WHETHER OR NOT EGT TENDED TO	
	1)1660-	FOLLOW RPM DROP. WE WOULD LIKE TO HAVE ANY SPECIFIC INFORMATION	
		ON ANY CASES WHERE EGT REMAINED ABOVE 500 DEGREES C WHILE RPM WAS	
25X1A	49800**	FALLING OFF. CAN COMMENT ON ANY TYPE OF ENGINE FAILURE	
	~man='	WHICH WOULD CAUSE EGT TO REMAIN ABOVE 500 DEGREES C WHILE RPM DECAYED	)
	_	TO IDLE OR BELOW.	
	<b>ምዛ</b> ነል"	2. THIS IS NOT INDICATION OF ANY ENGINE PROBLEM ON ART 385	
	vinites'	LOSS NOR DIRECTION INVESTIGATION BOARD POINTED BUT IS FOR INFO TO	
	******	CORRELATE AGAINST BW READOUTS.	

END OF MSG